

## Damage to Police Facilities in the Great East Japan Earthquake

	Damage to Police Headquarter	Damage to Police Station	Damage to Police Box
Iwate Prefecture Police	No damage	14 Stations	56 Places
Miyagi Prefecture Police	Damaged	24 Stations	134 Places
Fukushima Prefecture Police	Damaged (Headquarter and 1 Branch)	20 Stations and 4 Branches	58 Places
Total	Damaged (2 Headquarters and 1 Branches)	58 Stations and 4 Branches	248 Places

Note: As of June 4 2012

Source: National Police Agency "Police White Paper 2012" (IRIDeS revised the title)

## Detailed Information of the figure on the previous page

Title on the previous page		Damage to Police Facilities in the Great East Japan Earthquake
Point of displayed contents		Police headquarters were damaged in Miyagi and Fukushima Prefectures. 58 police stations, 4 branch stations, and 248 police boxes were damaged in Miyagi, Fukushima, and Iwate Prefectures.
Details of the source	Name of the source	National Police Agency “Police White Paper 2012” Chart 3 of Special Feature, Section 1 <June, 2012> (in Japanese)
	Title	Damage to Police Facilities in the Great East Japan Earthquake and Hanshin-Awaji Earthquake
	URL	<a href="https://www.npa.go.jp/hakusyo/h24/honbun/pdf/05_tokushu.pdf">https://www.npa.go.jp/hakusyo/h24/honbun/pdf/05_tokushu.pdf</a>
Keywords		damage, police headquarters, police station, police box
Data Number		01-071-0206 (Please specify this number when you make any inquiries about this sheet)