Damage Situation of Social Welfare Facilities by the Great East Japan Earthquake

Social Welfare and War Victims' Relief Bureau, Ministry of Health, Labor and Welfare, as of May 11, 2011

	Number of facilities	Number of affected facilities	Child welfare facilities		Welfare facilities for the elderly		Support facilities for persons with disabilities		Other Welfare facilities	
			Totally	partially	Totally	partially	Totally	partially	Totally	partially
			conapsed	destroyed	collapsed	destroyed	collapsed	destroyed	collapsed	destroyed
Iwate Prefecture	2,142	208	12	29	9	92	9	56	0	1
Miyagi Prefecture	3,712	333	13	131	2	54	11	122	0	0
Fukushima Prefecture	2 352	334	2	92	1	168	0	70	0	1
Total	7,206	875	27	252	12	314	20	248	0	2

Note:

- 1. Number of facilities are added up based on various statistics in 2009. Type of facilities are chosen from main types in which damage occurred.
- 2. The range of "totally collapsed" and "partially destroyed" is based on the judgment of the prefecture. "Partially destroyed" includes the case that a part of facilities is unusable, or some facilities are damaged.

Original data: Social Welfare and War Victims' Relief Bureau, Ministry of Health, Labor and Welfare Source: Ministry of Health, Labour and Welfare "Annual Health, Labour and Welfare Report 2011-2011"

Detailed Information of the figure on the previous page

Title on the previous page		Damage Situation of Social Welfare Facilities by the Great East Japan Earthquake				
Point of displayed contents		As to the social welfare facilities in the three affected prefectures in Tohoku, 875 facilities were damaged, and 59 facilities were completely collapsed. (As of May 13, 2011)				
Details of the source	Name of the source	Ministry of Health, Labor and Welfare "Annual Health, Labour and Welfare Report 2011-2011," Chapter 2, Page 146 Table <august, 2012=""> (in Japanese)</august,>				
	Title	(2) Damage Situation of Social Welfare Facilities in the Affected Area, Table Damage Situation (Medical Institution and Social Welfare Facility				
	URL	http://www.mhlw.go.jp/wp/hakusyo/kousei/11/dl/02-00.pdf				
Details of the original data	Name of the original data	Damage Situation of Social Welfare Facilities in the Great East Japan Earthquake (Medical Institution and Social Welfare Facility) (Prepared by Social Welfare and War Victims' Relief Bureau, Ministry of Health, Labor and Welfare, as of May 13, 2011) (in Japanese)				
	Title	(2) Damage Situation of Social Welfare Facilities in the Affected Area				
	URL	http://www.mhlw.go.jp/stf/shingi/2r9852000001yxlj-att/2r9852000001yy9a.pdf				
Keywords		social welfare facility, child, elderly, disability				
Dat	ta Number	01-151-0104 (Please specify this number when you make any inquiries about this sheet)				