

Number of Houses Newly and Re-suspended Water Supply by Aftershocks (Total)

Kiso-11

(house)

	4/7	4/11	4/12
2 Aomori	1,000		
3 Iwate	44,100		
4 Miyagi	180,700	300	11,500
5 Akita	20,200		
6 Yamagata	38,000		
7 Fukushima	20	124,600	
8 Ibaraki			300

Source : Ministry of Health, Labour and Welfare (MHLW) “Summary of Status Survey on damage of water supply facilities in the Great East Japan Earthquake”

Detailed Information of the figure on the previous page

Title on the previous page		Number of Houses Newly and Re-suspended Water Supply by Aftershocks (Total)
Point of displayed contents		Number of houses newly and re-suspended water supply by aftershocks in Miyagi Pref. is larger than other areas.
Details of the source	Name of the source	MHLW “Summary of Status Survey on damage of water supply facilities in the Great East Japan Earthquake”(2013)
	Title	Figure 2 Number of Houses Newly and Re-suspended Water Supply by Aftershocks (Total)
	URL	http://www.mhlw.go.jp/topics/bukyoku/kenkou/suido/tantousya/2012/dl/01_2_01.pdf
Details of the original data	Name of the original data	
	Title	
	URL	
Keywords		Water supply facilities, Newly suspended water supply, re-suspended water supply, Damage of water supply facilities
Data Number		01-155-0301 (Please specify this number when you make any inquiries about this sheet)