Damage to Hospitals and Function Status of Medical Care after the Great East Japan Earthquake

The original data is provided by Health Policy Bureau, Ministry of Health, Labour and Welfare (MHLW,) as of May 11,2011

	-	caused by oan Earthq	y Great East quake		Circumstances of medical care's function											
				Restricted acceptance of outpatient clinics			No Acceptance of outpatient clinics			Restricted acceptance of inpatients			No Acceptance of inpatient clinics			
		collapse		Right after damage	As of April 20	As of May 17	Right after damage		As of May 17	Right after damage		l As of May 17	Right after damage	As of April 20		
lwate Prefecture	94	4	58	54	5	3	7	3	3	48	7	2	11	5	4	
Miyagi Prefecture	147	5	123	40	17	5	11	6	2	7	13	5	38	11	7	
Fukushima Prefecture	139	2	108	66	20	11	27	12	12	52	22	14	35	24	20	
Total	380	11	289	160	42	19	45	21	17	107	42	21	84	40	31	

Note:

1. The range of "totally collapsed" and "partially destroyed" is based on the judgment of the prefecture. "Partially destroyed" may include the case that a part of building was unavailable to use and the case that some facilities was damaged.

2. The medical institutions accepting no patients in Fukushima Include those located in the Restricted Area and other areas where evacuation orders are received due to the accident at the Fukushima Daiichi Nuclear Power Plant of TEPCO.

3. With regard to Disaster base hospital, the number of inpatients were limited at the Iwate prefectural Kamaishi hospital (Iwate pref.), Ishinomaki Red Cross Hospital (Miyagi pref.), and also inpatients and outpatients were limited at Minamisoma City General Hospital (Fukushima pref.).

4. The status of some of hospital is yet to be confirmed.

Note: The original data is provided by "Damage situation (Medical institution Social welfare facility)" Source: This figure is taken from part of the figure of on page 146 of Chapter 2 of MHLW 'Annual Health, Labour and Welfare Report 2011-2012'

Statistical Database on the Great East Japan Earthquake, Global Centre for Disaster Statistics, IRIDeS, Tohoku Univ.

Detailed Information of the figure on the previous page

	he Figure on the evious page	Damage to Hospitals and Function Status of Medical Care after the Great East Japan Earthquake						
Point	of this Figure	Regarding the social welfare facilities in the three prefectures in Tohoku, 300 facilities were damaged, and 59 facilities were completely collapsed (as of May 13).						
Details of the source	Name of the source	This figure is taken from part of the figure on page 146, of Chapter 2 of the Ministry of Health, Labour and Welfare "Annual Health, Labour and Welfare Report 2011-2012" <august, 2011=""> (in Japanese)</august,>						
	Title and the number	Damage to Hospitals and Circumstances of Medical Care's Function by the Great East Japan Earthquake						
	URL	http://www.mhlw.go.jp/wp/hakusyo/kousei/11/dl/02-00.pdf						
Details of the original data	Details of the original data	Damage to the social welfare facilities in the Great East Japan Earthquake (medical institution = social welfare facility). (The original data is provided by the Health Policy Bureau, MHLW, as of July 11, 2011. Data only relating to the hospital of the Iwate, the Miyagi, and the Fukushima, was current as of September 15.) (in Japanese)						
	URL	http://www.mhlw.go.jp/stf/shingi/2r9852000001yxljatt/2r9852000001yy9a.pdf						
k	Keywords	Hospital, Medical care, Function of medical treatment						